

kogan

Slim Digital Kitchen Scales

KADIGTHSCAA

USER MANUAL



WARNING:

CHOKING HAZARD - Small parts and batteries. Not for children. Use with adult supervision only

Thank you for purchasing the Kogan Slim Digital Kitchen Scales.

To ensure proper operation and to maintain the lifespan and utmost accuracy of the scale, please read this manually carefully before use and keep a copy handy for future reference.

Key Features

- High precision strain gauge sensor system ensures more accurate weighing results.
- Stainless steel platform of high quality and modern design ensures the scale remains safe yet stylish.
- Capacity: 5000g
- Division: 1g
- Tare Function
- Auto Power Off
- Low battery and overload indicator
- Free switch between different units: g/fl.oz/lb : oz/ml
- Powered by 2 x CR2032 cell batteries that are packed in the box.

Buttons

ON/TARE key: Power on, power off and tare function.


UNIT key: Switch measuring units displayed (g/fl.oz/lb : oz/ml)

Operation

- Find the 2x CR2032 batteries in the box and locate the battery holder on the back of the scales. Open the cover, install the batteries into the holder and then reclose it (making sure the positive pole of the battery faces upwards).
- Place the scales on a steady, flat, hard surface.
- Press the “ON/TARE” button to switch the scales on. It will go through it's start-up process, and it will be ready once the LCD screen displays “0g”.




- Press the “UNIT” button and you can choose between the units “g”, “lb:oz”, “fl:oz” and “ml”.



- Put the container or ingredients that you want to weigh on the platform of the scale. The weight will be displayed on the LCD screen.



- Press the “ON/TARE” button to clear the weight of whatever is on the platform, at which point the screen will show “0g” and “Tare”. You can then put ingredients inside the container or add more ingredients to the platform, where the weight of the newly added produce will be displayed on the LCD screen.



- Continue to use the “ON/TARE” button and you can get respective weights on more things through repeating the tare process. When all of the product is eventually removed from the platform, the total weight will be shown on the screen.



- Press the “ON/TARE” button to switch the scales off when the screen shows “0g” if no more weighing is needed. The scales will also shut off automatically if no buttons are pressed and nothing is weighed for a certain time.

Caution

Please change the batteries when “Lo” appears on the screen, which indicates that the battery is out of power.



“EEEE” shown on the screen indicates overload.



Attention

1. Please put the scales on a hard and flat surface. (A clean, hard table is best) and make sure it is steady before use.
2. The maximum weight that the scales can measure is 5000g, which is the weight BEFORE the tare.
3. Please use a soft tissue with some rubbing alcohol or glass cleaner to clean the surface of the platform if it gets dirty. Do not use soap or other chemicals. Keep the unit away from water, corrosive liquids, heat or extreme coldness.
4. The scale is a high precision measurement device. Never knock it heavily or try to disassemble it, and carry it carefully when moving it to a different location.
5. The scale is for family and household use only, and is not suitable for professional or commercial use.
6. Please check the battery if the scale malfunctions. If the problems persist after the batteries have been replaced, please contact the Kogan customer support team via email or phone for further assistance.

